

There is a covered porch over the front entrance and a rear deck off of the restaurant and lounge. The building is heated with two oil-fired boiler and one wood fired boiler. Air conditioning is provided seasonally through window-mounted units. There is a 200 Amp electrical entrance. The building was built prior to 1978 and may contain lead paint.

Building Sketch

