




21-50-13
0.61 AC

21-50-36
0.60 AC

21-50-37
0.57 AC

21-50-63
0.57 AC

21-50-64
0.55 AC

21-50-12.1
0.69 AC

21-50-91.2
1.69 AS

21-50-91.3
0.80 AS

21-50-90
0.57 AC

21-50-86
0.60 AC

21-50-92
0.70 AC

21-50-91.1
0.67 AS

21-50-89
0.57 AC

21-50-88
0.69 AC

21-51-01
0.84 AS

21-51-02
1.16 AS

21-51-13
0.78 AS

21-51-14
1.1 AC

21-51-15
1.2 AC

21-51-04
1.70 AS

21-51-03
1.06 AS

21-51-12
0.77 AS

21-51-20
1.0 AC

21-51-05
1.49 AS

21-51-11
0.80 AS

21-51-10
0.70 AS

21-51-09
0.91 AS

21-51-21
0.94 AC

21-51-06
2.43 AS

21-51-07
0.71 AS

21-51-08
0.64 AS

21-51-22
0.91 AC

24-50-39
0.06 AC

24-50-40
0.75 AC

24-50-51
0.93 AC